


PERMEABILITY VERSUS POROSITY

Routine Samples

Crossroads Environmental WDW 315 No. 1 East Conroe Field

Montgomery County, Texas File No. H-3260



ייים חחפר ב